# VALUE GRID INSTRUCTIONS

1. ASSEMBLE PANELS IN ORDER

Each panel is labeled in numerical order and should be assembled starting for 1 and so forth. Side panels connect to back panels by sliding a 20" pin through the designated hinges as shown below. Side Panels also connect to cross bracing by sliding a 5" pin through the designated hinges on the panels and cross bracing.

5" CROSS BRACING PIN

20" SIDE PANEL PIN

5" CROSS BRACI NG PIN

2. ATTACH HEADER PANELS

Connect the back headers to the side panels by sliding a 5" pin through the designated hinges on the side panel. After your back headers are connected the front header can be hung on the back header.

FRONT PANEL HANGS ON BACK PANEL

5" HEADER PANEL PIN

3. ATTACH COUNTER TOP

The counter top sits on top of the designated hinges on the side panels of the market, by sliding a 20" pin through the hinges and tubing on both sides of the counter top underneath.

20" COUNTER TOP PIN

GTP
GRAPHICS THAT POP

VALUE GRID INSTRUCTIONS

4. PLUG LIGHTS INTO CORDS

Connect the cord on the back panel to the lighting on the side panel.

CONNECT CORD →

5. HANGING BACK WALL GRAPHICS

Hanging graphic has a plank attached to the top that is designed to sit in the brackets on the side panel.

BACK VIEW

HANG PLANK W/BACK GRAPHIC →

FRONT VIEW

BACK VIEW

6. PLACE SHELVING THEN ADD PRODUCT

To insert shelves loosen the designated bolts on side side panel enough for the shelf to slide on to bolts.

GTP
GRAPHICS THAT POP

SIDE PANEL

35"

92"

HEADER BRACKET

CROSS BRACING

BACK PANEL PINS

SHELF HOLES

COUNTER TOP 2

COUNTER TOP 1

CROSS BRACING

BACK PANEL PINS

CROSS BRACING

BASE

BACK VIEW-COOLERS

FRONT VIEW-COOLERS

ON CROSS BRACING INSERT 2" LONG BOLTS W/WASHERS INTO PRE-DRILLED HOLE

CROSS BRACING

CROSS BRACING

CROSS BRACING

CROSS BRACING

CROSS BRACING

CROSS BRACING

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS

CROSS BRACING PINS